



## Legislation Text

---

**File #:** AUT 18-052, **Version:** 1

---

Consideration of and action on authorizing funds to repair Patrick's Cabin.

Patrick's cabin is in need of structural repairs and the following are the needed repairs:

- Repairs and replace rotten logs to match existing logs and replace corner ends
- Power wash and caulk where needed
- Reseal exterior of log home to give a rustic finish
- Foundation repair to the building
- General builder's fee

Required repairs are necessary for the structural integrity and public use of the facility.

\$9,680.00	Repairs and replace rotten logs to match existing logs and replace corner ends
\$6,975.00	Power wash and caulk where needed and reseal exterior of log home to give a rustic finish
\$3,200.00	General builder's fee
\$5,000.00	Landscaping
<u>\$3,500.00</u>	<u>Foundation repair to the building</u>
<b>\$28,355.00</b>	<b>Total</b>

Funds are available in Fund 11 (Special Revenue) Dept. 605 - Historical Preservation (Hotel Occupancy Tax).

Acceptance of funds to repair Patrick's Cabin.